











□□□□□□-□□□□□□ :

□□□□□ □□□□□□□□□□□□□□□□□□□□□□ □□□□□ **Mousse** □□□

XINXIN INDUSTRIAL CO., LTD
R. 7, Huha building, 4079 Longfeng Road, Shenzhen, China

Sample Description : PZDA B-01V6L
Style No. : 302M
Item No. : Bsp-302B

All above test item and its relevant information regarding to the submission are provided and confirmed by the applicant. SGS is not liable to either the test item or its relevant information, in terms of the accuracy, authority, reliability and/or magnify accordingly.

SGS Ref No. : CANHG2109097401
Sample Receiving Date : May 28, 2021
Test Performing Date : May 28, 2021 to Jun 01, 2021
Test Performed : Selected test(s) as requested by applicant.

Test Result Summary

No.	Test(s) Requested	Result(s)	Comments
1	Regulation (EC) No 1935/2004 of the European Parliament and of the Council of 27 October 2004 Council of Europe Resolution C(2014) 233-EN/2014/0233 (REACH) (MCL)	Pass	-

For further details, please refer to the following page(s):

Signed for and on behalf of
SGS-CEIC Standards Technical Services Co., Ltd. Shunde Branch




Authorized Signatory



SGS-CEIC Standards Technical Services Co., Ltd. Shunde Branch
Address: No. 1, Zhongyuan Road, Shunde, Guangdong, P.R. China
Tel: +86 (0)757 2202 2202 Fax: +86 (0)757 2202 2202
E-mail: sgs@sgs.com.cn
Website: www.sgs.com.cn

Member of the SGS Group (SAS 84)

Photo Appendix:



CANHG2109097401
CAN2109097401

Remark: This test was subcontracted to SGS-CEIC Standards Technical Services Co., Ltd. Guangzhou Branch.

End of Report



SGS-CEIC Standards Technical Services Co., Ltd. Guangzhou Branch
Address: No. 1, Zhongyuan Road, Guangzhou, Guangdong, P.R. China
Tel: +86 (0)20 8222 2222 Fax: +86 (0)20 8222 2222
E-mail: sgs@sgs.com.cn
Website: www.sgs.com.cn

Member of the SGS Group (SAS 84)

□□□□□ □□□□□□ □□□□□□

