9 □□□ □□□ □□□□□ □□□□ □□□□□ DIY □□□ □□□ □□□□□□□□□ □□□□□□□□□□□ □□□□ □□□□□□□□ □□□□□

□□□□□□□□□:

1). □□□□□□ □□□□ □□ □□□ □□□□ □□□ □□□□ □□

2). □□□□ □□□□□□□□ □□□□□ □□□□□

3). □□□□□□□ □□□ □□□□□□

□□□□□ □□□□□□□□ :


7 Inch
2 Inch

□□□□□□□□ □□□□□□□:

□□□□□□□□ **NewPlanet** □□□□□□□□ □□, □□□□□□□ **2010** □□□ □□□□□□□, □□□□□□ □□ □□□□□□□□□□□□ □□□ □□□□□□ □□□□□□□□□□□□□□□□ □□□ □□ □□□ □□□ □□□□□ □□ □□□□□ □□□ □□□□□□□ □□□□□□□□□□□□□□ □□□ , □□ □□□□ □□□□□□□□ □□□□□□□□ □□□□ □□□, □□ □□□□□□□□ □□□□□□ □□□□□□□□□□□□□ □□ □□□□□□□ □□□□ □□ □□□ □□□□□ □□□□□ □□□□□ □□ □□□ □□□

□□□□ □□□□□, □□□□□ □□□□□□ □□□ □□ □□□□□, □□□□□□ □□□□□□□ □□□ □□□□ □□□ □□□□□ □□□□□.

SGS

Test Report No.SCHL2109097103A Date: Jun 03, 2021 Page 1 of 4

KINXIN INDUSTRIAL CO., LTD
R. T. Hu He building, 4078 Longgang Road, Shenzhen, China

Sample Description : PIZZA SHOVEL
Style No. : 3DDH
Item No. : Shop-3038

As above test item and its relevant information regarding to the submission are provided and confirmed by the applicant, SGS is not liable to either the test item or its relevant information, in terms of the accuracy, authority, reliability and integrity accordingly.

SGS Ref.No. : CANHG2109097401
Sample Receiving Date : May 28, 2021
Test Performing Date : May 28, 2021 to Jun 01, 2021
Test Performed : Selected test(s) as requested by applicant

Test Result Summary

No.	Test(s) Requested	Result(s)	Comments
1	Regulation (EC) No 1935/2004 of the European Parliament and of the Council of 27 October 2004 Council of Europe Resolution CM/Res(2013)9 Silicone rubber	Pass	/
For further details, please refer to the following page(s):			

Signed for and on behalf of
SGS-CSTC Standards Technical Services Co., Ltd. Shunde Branch

Show Zhang
Authorized Signatory

Member of the SGS Group (SGS SA)

SGS

Test Report No.SCHL2109097103A Date: Jun 03, 2021 Page 4 of 4

Photo Appendix:



CANHG2109097401
CAN21-080974.001

Remark: This test was subcontracted to SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch.

End of Report

Member of the SGS Group (SGS SA)